

SoundExpert 721-821 Release History



List of changes made to Larson Davis SoundExpert 721-821¹

SoundExpert 721-821 Version 1.002

July 2023

1. The decreased run time, increased power consumption, created in 1.001 has been rectified.

SoundExpert 721-821 Version 1.001

June 2023

1. Fixed issue where the meter would lock up when entering sleep mode.
2. When entering sleep mode, without OBA enabled, data could become corrupted.

SoundExpert 721-821 Version 1.000

June 2023

1. Initial Release

¹ Note: Numbers in parenthesis such as "(3210)" are an internal tracking number.